



7 September 2016

(16-4767)

Page: 1/1

Committee on Technical Barriers to Trade

Original: English

NOTIFICATION

Corrigendum

The following communication, received on 5 September 2016, is being circulated at the request of the Delegation of the United States of America.

TITLE: Parts and Accessories Necessary for Safe Operation; Inspection, Repair, and Maintenance; Correction

AGENCY: Federal Motor Carrier Safety Administration (FMCSA), DOT

ACTION: Final rule; correction

SUMMARY: This notice makes corrections to a final rule published in the Federal Register on 22 July 2016, regarding amendments to the Federal Motor Carrier Safety Regulations in response to several petitions for rulemaking and NTSB recommendations. The Agency makes several minor clerical corrections regarding the rear license plate lamp requirements and the periodic inspection requirements for antilock brake systems (ABS).

This rule is effective 2 September 2016.

https://members.wto.org/crnattachments/2016/TBT/USA/16_3697_00_e.pdf
